



**Important!**

Please give copies to all  
your VW Technicians

# Technical Bulletin

Subject: Procedure After Restoring Electrical Power

Group: 01

Number: 99-15

Model(s): All

1999▶

Date: Aug 25, 1999

Supersedes T.B. Group 01 Number 99-12 Dated July 22, 1999

Superseded due to addition of Labor  
Operation on Page 2

## Service

When electrical power has been restored etc. after the battery has been disconnected, perform adaptation / reset items listed below to ensure proper vehicle function.

### **WARNING!**

**Disconnect battery Ground (GND) strap before working on electrical system.**

**Ensure there is no person inside vehicle when connecting battery Ground (GND) strap.**

### **Note:**

- ◆ *The following procedures are abbreviated. if necessary, complete instructions can be found in the appropriate Repair Manuals.*
- ◆ *For vehicles equipped with Immobilizer, the Key code is maintained when power is interrupted for any reason. Therefore, recoding the key/instrument cluster is not required.*
- Check all systems for stored DTC's.
- Make appropriate repairs, if necessary.
- Clear DTC memory, if DTC's were found.
- Set engine basic settings (Electronic Throttle Control Adaptation).
- Set transmission basic settings.
- Set Climatronic, power window, and power seat adaptation.

(Cont. on Page 2)



**Important!**

Please give copies to all  
your VW Technicians

# Technical Bulletin

---

Perform the following as necessary:

- Check Readiness code and set.
- Reset clock and radio anti-theft code.

**When procedure applies to vehicles with-  
in the New Vehicle Limited Warranty, use  
the following:**

**Part Identifier: 2700**

**Labor Operation: 2700713 30TU**